	Туре	L #	Hits	Search Text	DBs	Time Stamp
1	BRS	L1		(water near3 (measur\$ or monitor\$)) and (automat\$ or (self near1 calibrat\$))	USPAT; EPO; JPO; DERWEN T	2003/09/29 20:42
2	BRS	L2		<pre>(water near3 (measur\$ or monitor\$)) and (automat\$ or (self near1 calibrat\$))</pre>	EPO; JPO; DERWEN T	2003/09/29 20:53
3	BRS	L3 _.	7	<pre>2 and (ion near1 (sensitive or selective))</pre>	EPO; JPO; DERWEN T	
4 ·	BRS	L4	32	i	EPO; JPO; DERWEN T	2003/09/29 20:46
5	BRS	L 5	32	4 not 3	DERWEN T	2003/09/29 20:46
6	BRS	L6	838	<pre>(water near2 (quality)) and (automat\$ or (self near1 calibrat\$))</pre>	EPO; JPO; DERWEN T	2003/09/29 21:05
7	BRS	L7	0		EPO; JPO; DERWEN T	: 1
8	BRS	L8	52	6 and (electrode or probe)	EPO; JPO; DERWEN T	2003/09/29 20:54
9	BRS	L9	47	8 not 5	EPO; JPO; DERWEN T	2003/09/29 20:54
10	BRS	L10	2708	<pre>(water near2 (quality or monitor\$ or measur\$)) and (automat\$ or (self near1 calibrat\$))</pre>	EPO; JPO; DERWEN T	2003/09/29 21:06
11	BRS	L11	2713	(automat\$ or (self near1	EPO; JPO; DERWEN T	2003/09/29 21:08

	Туре	L#	Hits	Search Text	DBs	Time Stamp
12	BRS	L12	3		EPO; JPO; DERWEN T	2003/09/29 21:08
13	BRS	L13	0		EPO; JPO; DERWEN T	2003/09/29 21:08
14	BRS	L14	1466	<pre>(water near2 (quality or monitor\$ or measur\$)).ab.</pre>	USPÄT	2003/09/29 21:43
15	BRS	L15	: 3//	14 and (electrodes or probes)	USPAT	2003/09/29 21:26